The impact of EUV mask residual-type defect thickness on wafer printability

Tsuyoshi Amano, Susumu lida, Ryoichi Hirano, Tsuneo Terasawa and Hidehiro Watanabe EUVL Infrastructure Development Center, Inc.

Yuichi Inazuki

Dai Nippon Printing Co., Ltd.


Summary

- ◆The residual-type bridge defects were fabricated by etching full-height defects using EB etching tool.
- **♦** The residual-type defects were printed on wafer.
 - The 2.9 and 8.2-nm-high TaBN layer cause 30 and 40 percent of reflectance reduction respectively.
 - No printable ML damage was observed around EB etching process area.
 - At outer focus range, the 2.9-nm-high bridge defects causes more than 10 percent of CD error.


Introduction

The impact of residual-type defects is not clear while the impact on wafer printing by EUV mask pattern defects with various shapes has been already investigated using programmed defect masks.

This presentation describes the experimental results by wafer printing using Small Field Exposure Tool and computer simulation results. In addition the fabrication method of programmed residual-type mask defects is also described.



Defect thickness target TaBN thickness vs EUV reflectivity Simulator: EM-Suite™



Target height of the residual-type defects were set to 3, 8, 18 and 33 nm for printability test, because the variation in the reflectivity caused by thickness error of TaBN happens to be small.

Preparation of the residual-type programmed defect

Mask pattern: hp 225 nm L/S (900 x 225 nm, 66-nm-high)
Defect height control: MeRiT HR32

Fully etched defect (0-nm-high)


Original defect


Height of the residual-type defect 33.1 nm 17.8 nm 8.2 nm


Absorber ML Defect

AFM images

SEM images








2.9 nm

The residual-type defects were well fabricated without ML damage.

Wafer printability of the residual-type defects

Printing tool: SFET (NA: 0.3, sigma (inner/outer): 0.3/ 0.7, Mag.: 1/5)



- The full etched defect was not printed on the wafer within +/- 100 nm focus range.
- ✓ The residual-type defects are apparently printed on wafer even if its height is only 8.2 nm.
- The calculated images show 2.9-nm-thick residual-type defect causes intensity loss of EUV light.


Acknowledgements

DNP: Tsukasa Abe

Toshiba: Shingo Kanamitsu


EIDEC: Shunko Magoshi and Julius Santillan

Measured and calculated CDs



The 2.9-nm-high residual-type bridge defect causes more than 10 % of CD error at outer focus range.

Bridging size dependency



The residual-type bridging defects will cause strict CD degradation, and should be repaired after detected by inspection tool.

This work is supported by New Energy and Industrial Technology Development Organization (NEDO).



